
KOV
sync
unused
FM
unused
-15V
out1
-1V
gnd
mute
unused
saw out
+15V
+10V
unused
lin FM
PW up
PW down
waveform
3S1 bead
3S1 bead
10µ 25V
15µ 16V
1µ
HF
10k
1n
100p
22p
LF412
100k init
TEMPCO
TL072
LM393
oct /V
10k
BAT42
220p
OFFSET
DUS
10p
IC6
IC4
IC5
IC3
tracking
1k
offset
100k
IC2
IC1
TL074
4051
4066
4011
MMCD