
KOV
sync
octaves CV
FM
divide CV
-15V
out A
-1V
gnd
mute A
mute B
out B
+15V
+10V
unused
lin FM
PW up CV
PW down CV
waveform CV
3S1 bead
3S1 bead
2009-03-15
BERGEOTRON
ADVANCED VCO
sq
lin FM
tri
LF lin
freq.offset
slope track
2F out
2F offset
cs offset
cs out
tri out
lin bs
saw out
up CV
down CV
sq out (odd)
slope offset
pulse out
double pulse out
sq
even out
tri
saw shape
out
sine out
sine offset
sine sym
sine shape
mute A
out A
mute B
out B
fifths trim
octaves trim
divide CV
divide offset
octaves CV
WF CV
TEMPO
CV
TL072
TL064
TL062
LM393
CA3080
CA3046
4066
4051
4013
4584
LM311
100n
220p
4n7
20k
10k
1k
100k
100p
1n
10µ
10µ 25V
470p
3n3
22p
330
22µ 25V
10µ 25V