

- KOV
- lin FM 1
- *unused*
- FM CV 1
- PW CV 1
- 15V
- VCO1 out
- *unused*
- gnd
- saw/pulse 1
- sync on
- VCO2 out
- +15V
- +10V
- tuning LED
- lin FM 2
- FM CV 2
- PW CV 2
- saw/pulse 2

